

Environment Protection Licence Monitoring Data - Air



Project Name: Coffs Harbour Bypass
Monitoring Period:
EPL Number: 21766
Licensee: Gamuda Berhad and Ferrovial Agroman (Australia) Pty. Ltd.
Premise Address: Coffs Harbour NSW 2450
Public Register: <https://apps.epa.nsw.gov.au/prpoeoapp/Detail.aspx?instid=21766&id=21766&option=licence&searchrange=licence&range=POEO%20licence&prp=no&status=Issued>
Relevant EPL Condition/s: M2.2

| Monitoring Point | Start Date | End Date | Date Data Obtained | Solid Particles (g/m ² /month) | Monitoring Frequency | Comment |
|------------------|------------|----------|--------------------|---|----------------------|---|
| DDG1 | 24-05-23 | 23-06-23 | 03-07-23 | 0.9 | Monthly | |
| DDG2 | 24-05-23 | 23-06-23 | 03-07-23 | 4.1 | Monthly | FGJV vegetation clearing and topsoil stockpiling on Englands Rd contributing to DDG dust level. |
| DDG3 | 24-05-23 | 23-06-23 | 03-07-23 | 0.3 | Monthly | |
| DDG4 | 24-05-23 | 23-06-23 | 03-07-23 | 4.4 | Monthly | FGJV basin construction and vegetation clearing ongoing near DDG. |
| DDG5 | 24-05-23 | 23-06-23 | 03-07-23 | 0.3 | Monthly | |
| DDG6 | 24-05-23 | 23-06-23 | 03-07-23 | 2.2 | Monthly | |
| DDG7 | 24-05-23 | 23-06-23 | 03-07-23 | 0.3 | Monthly | |
| DDG8 | 24-05-23 | 23-06-23 | 03-07-23 | 3.5 | Monthly | No FGJV works in area. Only works in area is TfNSW dewatering bays. Other potential dust sources could be vehicles on the road. |
| DDG9 | 24-05-23 | 23-06-23 | 03-07-23 | 0.3 | Monthly | |
| DDG10 | 24-05-23 | 23-06-23 | 03-07-23 | 1.1 | Monthly | |
| DDG11 | 24-05-23 | 23-06-23 | 03-07-23 | 2.2 | Monthly | Construction of sediment basin and bulk earthworks occurring within the vicinity of DDG. |
| DDG12 | 24-05-23 | 23-06-23 | 03-07-23 | 1.2 | Monthly | |
| DDG13 | 24-05-23 | 23-06-23 | 03-07-23 | 0.4 | Monthly | |
| DDG14 | 24-05-23 | 23-06-23 | 03-07-23 | 0.5 | Monthly | |
| DDG15 | 24-05-23 | 23-06-23 | 03-07-23 | 0.6 | Monthly | |

